



Photo # 1

Date: 11/3/09

Time: 0938

Description: Accidental Photo of floor (IMGP0849)

Photographer: M. Moloney




Photo # 2

Date: 11/3/09

Time: 0938

Description: CF-1 Tanks and a tote inside plant building (IMGP0850)

Photographer: M. Moloney




Photo# 3

Date: 11/3/09

Time: 0938

Description: Sodium hydroxide tank inside plant building (IMGP0851)

Photographer: M. Moloney



Photo# 4

Date: 11/3/09

Time: 0941

Description: Tanks and piping inside plant building (IMGP0852)

Photographer: M. Moloney



Photo# 5
Date: 11/3/09
Time: 0943
Description: Drum and tote storage area (IMGP0853)
Photographer: M. Moloney




Photo# 6
Date: 11/3/09
Time: 0944
Description: Drum and tote storage area (IMGP0854)
Photographer: M. Moloney



Photo# 7
Date: 11/3/09
Time: 0944
Description: Drum and tote storage area (IMGP0855)
Photographer: M. Moloney



Photo# 8
Date: 11/3/09
Time: 0944
Description: Drum and tote storage area (IMGP0856)
Photographer: M. Moloney



Photo# 9

Date: 11/3/09

Time: 0945

Description: Tote labeled "DRIMAX 1235B" (IMGP0857)

Photographer: M. Moloney



Photo# 10

Date: 11/3/09

Time: 0945

Description: Tote labeled "Superfloc 1422RS" (IMGP0858)

Photographer: M. Moloney



Photo# 11

Date: 11/3/09

Time: 0946

Description: Tote with "17% caustic" written on label (IMGP0859)

Photographer: M. Moloney



Photo# 12

Date: 11/3/09

Time: 0947

Description: Drums in storage area with written descriptions that include: "pure aluminum chloride 27%" and "TCLP #..." (IMGP0860)

Photographer: M. Moloney



Photo# 13

Date: 11/3/09

Time: 0948

Description: Drums, totes and super sacks (IMGP0861)

Photographer: M. Moloney



Photo# 14

Date: 11/3/09

Time: 0949

Description: Corroded drum in storage area (IMGP0862)

Photographer: M. Moloney



Photo# 15

Date: 11/3/09

Time: 0949

Description: Drum in storage area (IMGP0863)

Photographer: M. Moloney




Photo# 16

Date: 11/3/09

Time: 0950

Description: Storage tanks and totes inside plant building (IMGP0864)

Photographer: M. Moloney




Photo# 17
Date: 11/3/09
Time: 0951
Description: Storage tanks inside plant building (IMGP0865)
Photographer: M. Moloney



Photo# 18
Date: 11/3/09
Time: 0959
Description: Sample storage (IMGP0866)
Photographer: M. Moloney




Photo# 19
Date: 11/3/09
Time: 1000
Description: Sample storage (IMGP0867)
Photographer: M. Moloney



Photo# 20
Date: 11/3/09
Time: 1000
Description: Sample storage (IMGP0868)
Photographer: M. Moloney



Photo# 21
Date: 11/3/09
Time: 1000
Description: Sample storage (IMGP0869)
Photographer: M. Moloney



Photo# 22
Date: 11/3/09
Time: 1003
Description: Loading/Unloading piping at garage door (IMGP0870)
Photographer: M. Moloney



Photo# 23

Date: 11/3/09

Time: 1003

Description: Tanks Nos. D-302 & D304 labeled "Oil Emulsion", "8000" (IMGP0871)

Photographer: M. Moloney



Photo# 24

Date: 11/3/09

Time: 1004

Description: Tank inside dike (IMGP0872)

Photographer: M. Moloney



Photo# 25

Date: 11/3/09

Time: 1004

Description: Tank inside dike (IMGP0872)

Photographer: M. Moloney



Photo# 26

Date: 11/3/09

Time: 1006

Description: Tank No. D-202 labeled "Sodium Acetate" (IMGP0874)

Photographer: M. Moloney



Photo# 27

Date: 11/3/09

Time: 1006

Description: Tank No. D-200 labeled "Oil Emulsion" (IMGP0875)

Photographer: M. Moloney



Photo# 28

Date: 11/3/09

Time: 1012

Description: Tank No. D-218 (IMGP0876)

Photographer: M. Moloney




Photo# 29

Date: 11/3/09

Time: 1012

Description: Drip buckets under piping (IMGP0877)

Photographer: M. Moloney



Photo# 30

Date: 11/3/09

Time: 1014

Description: Dumpster with waste material including buckets and floor dry material (IMGP0878)

Photographer: M. Moloney



Photo# 31

Date: 11/3/09

Time: 1014

Description: Dumpster with waste material (IMGP0879)

Photographer: M. Moloney



Photo# 32

Date: 11/3/09

Time: 1014

Description: View inside plant (IMGP0880)

Photographer: M. Moloney




Photo# 33

Date: 11/3/09

Time: 1016

Description: Piping/drain located outside at south end of the facility (IMGP0881)

Photographer: M. Moloney



Photo# 34

Date: 11/3/09

Time: 1017

Description: Location of Piping/drain located outside at south end of the facility (IMGP0882)

Photographer: M. Moloney



Photo# 35

Date: 11/3/09

Time: 1017

Description: Storage tanks located outside of building at south end of the facility (IMGP0883)

Photographer: M. Moloney



Photo# 36

Date: 11/3/09

Time: 1017

Description: Storage tanks located outside of building at south end of the facility (IMGP0884)

Photographer: M. Moloney



Photo# 37

Date: 11/3/09

Time: 1018

Description: Storage tanks Nos. 501 and 502 located outside of building (IMGP0885)

Photographer: M. Moloney



Photo# 38

Date: 11/3/09

Time: 1018

Description: Storage tanks Nos. 500, 501 and 502 located outside of building (IMGP0886)

Photographer: M. Moloney



Photo# 39

Date: 11/3/09

Time: 1022

Description: Piping at southwest corner of building (IMGP0887)

Photographer: M. Moloney



Photo# 40

Date: 11/3/09

Time: 1022

Description: Trench at southwest corner of building (IMGP0888)

Photographer: M. Moloney



Photo# 41
Date: 11/3/09
Time: 1022
Description: Trench at southwest corner of building (IMGP0889)
Photographer: M. Moloney



Photo# 42
Date: 11/3/09
Time: 1022
Description: Trench at southwest corner of building (IMGP0890)
Photographer: M. Moloney




Photo# 43
Date: 11/3/09
Time: 1025
Description: East side of building looking north (IMGP0891)
Photographer: M. Moloney



Photo# 44
Date: 11/3/09
Time: 1026
Description: East side of building looking south (IMGP0892)
Photographer: M. Moloney



Photo# 45
Date: 11/3/09
Time: 1026
Description: Area southeast of building (IMGP0893)
Photographer: M. Moloney



Photo# 46
Date: 11/3/09
Time: 1037
Description: Trench at southwest corner of building (IMGP0894)
Photographer: M. Moloney




Photo# 47

Date: 11/3/09

Time: 1037

Description: Trench along west side of building (IMGP0895)

Photographer: M. Moloney




Photo# 48

Date: 11/3/09

Time: 1037

Description: Trench at southwest corner of building (IMGP0896)

Photographer: M. Moloney



Photo# 49

Date: 11/3/09

Time: 1038

Description: West side of building (IMGP0897)

Photographer: M. Moloney

